MATERIAL SAFETY DATA SHEET

"Essentially Similar" to U. S. Department of Labor Form LSB-00S-4 DPM 966

SECTION I IDENTIFIC	ATION OF PRODUC	T. 124 - 17 - 17 - 17 - 17 - 17 - 17 - 17 - 1				
MANUFACTURER'S NAME	CLIEMTONT	EMERGENCY TELEPHONE NO. 213/861-1211				
McGean Chemical Co., Inc., CEE-BEE	CHEMICAL					
9520 E. CeeBee Drive, Downey,	CA 90241	MAY 28 1982				
trade name and synonyms						
CEE-BEE ALUMALOY P						
CHEMICAL NAME AND SYNONYMS						
A multipurpose cleaner						
CHEMICAL FAMILY COMPOUND	MOLECULAR FORMULA	blend				

COMPONENT	%	LIMIT VALUE	COMPONENT	%	THRESHOI LIMIT VALUE
		(UNITS)			(UNITS)
Sodium chromate -					
less than	0.1%				
Dipropylene glycol					
methyl ether	5-10	300 ppm			

BOILING POINT (°F.)	above	212	SPECIFIC GRAVITY (H ₂ O=1)		1.05
VAPOR PRESSURE (mm Hg.)	below	23	PERCENT VOLATILE BY VOLUME (%)		92
VAPOR DENSITY (AIR = 1)	same as	water	EVAPORATION RATE (water	apı	orox. 1
SOLUBILITY IN WATER	200m i nu	soluble			uud de la

	SECTION IV FIRE AND E	XPLOSION HAZARD DATA	PRITER TO	
	o and including oiling point	FLAMMABLE LIMITS (PERCENT BY VOLUME)	LOWER n/a	UPPER
FIRE-EXTINGUISHING MEDIA	n/a			
SPECIAL FIRE-FIGHTING PROCEDURE	s n/a		ar e ^l Santonio	
UNUSUAL FIRE AND EXPLOSION HA	none			

THIS PRODUCT SAFETY DATA SHEET IS OFFERED SOLELY FOR YOUR INFORMATION, CONSIDERATION AND INVESTIGATION.

McGEAN CHEMICAL COMPANY, INC. PROVIDES NO WARRANTIES, EITHER EXPRESS OR IMPLIED, AND ASSUMES NO RESPONSIBILITY FOR THE ACCURACY OR COMPLETENESS OF THE DATA CONTAINED HEREIN.

SECTION V HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE

10,000 mg/M³

EFFECTS OF OVEREXPOSURE

Eye irritant, mild skin irritant

EMERGENCY AND FIRST AID PROCEDURES

For skin or eye contact, flush with water

SECTION VI REACTIVITY DATA					
	UNSTABLE		CONDITIONS TO AVOID		
STABILITY	STABLE	ж			
INCOMPATIBILITY (A		erial	s that react violently with water		
HAZARDOUS DECO	MPOSITION PRODUCTS.		n/a		
HAZARDOUS	MAY OCCUR	,	CONDITIONS TO AVOID		
POLYMERIZATION	WILL NOT OCCUR	x			

SECTION VII SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Flush away with water, or absorb on clay

waste Disposal Method COMPLY WITH ALL FEDERAL, STATE & LOCAL ENVIRONMENTAL REGULATIONS. Release to sewer, adjusting pH to meet local regulations if required, or landfill

SECTION VIII SPECIAL PROTECTION INFORMATION					
RESPIRATORY PROTE	CTION (Specify type) not	normally	requir	ed	NIOSH CERTIFIED EQUIPMENT LIST (SEE PUBLICATION NO. 80-144)
	LOCAL EXHAUST			SPECIAL	· · · · · · · · · · · · · · · · · · ·
VENTILATION	MECHANICAL (Generall			OTHER	
			eye protection goggles or face shield		
OTHER PROTECTION	EQUIPMENT				

SECTION IX SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

Store in cool, dry place. Preferred storage temperatures—below 110°F and above 32°F.

OTHER PRECAUTIONS

9520 EAST CEE BEE DRIVE · DOWNEY, CALIFORNIA 90241 · TELEPHONE (213) 861-1211

Corporate Headquarters: McGean Chemical Company, Inc. • 1250 Terminal Tower • Cleveland, Ohio 44113 • Telephone (216) 621-6425 • Telex 98-0403

CEE-BEE ALUMALOY P

General Description:

An economical, effective, silicated, slightly chromated cleaner for multipurpose cleaning.

Advantages:

- 1. Low use cost.
- 2. Biodegradable detergents
- 3. Effective on a wide range of soils.
- 4. Efficient used cold, with steam cleaning equipment, or as a solvent emulsion.
- 5. Safe for use on all common metals, glass, tile, concrete, plastics and good quality paint.

Intended Use:

1. Heavy Degreasing

OPERATION: Mix 1 part CEE-BEE Alumaloy P, undiluted or diluted with equal parts of water, with 3 parts high flash mineral spirits and agitate vigorously to form stable emulsion. Apply emulsion to soiled surface and allow to dwell 1 to 5 minutes. Agitate with brush, or mop to emulsify soil. Flush surface with flowing water rinse, or remove soil with wet mop or cloth.

2. General Purpose Cleaning

OPERATION: Dilute 1 part CEE-BEE Alumaloy P with 5 to 10 parts water. Spray, brush, mop or wipe CEE-BEE Alumaloy P solution onto soiled surface. Agitate lightly and rinse with flowing water, or wipe with cloth dampened with water.

3. Steam Cleaning

OPERATION: For steam cleaning machine, dilute CEE-BEE Alumaloy P with 20 to 30 parts water. Control flow of CEE-BEE Alumaloy P solution into heater so that adequate foam is generated at work surface.

4. Immersion Tank Degreasing

OPERATION: Mix 1 part CEE-BEE Alumaloy P with 1 to 3 parts aromatic

Continue on other side

Intended Use (Cont.)

petroleum solvent (to reduce danger of fire, a solvent with a flash point about 100°F is recommended). Vigorously agitate CEEBEE Alumaloy P/solvent mixture by bubbling compressed air through the liquid. Immerse parts to be degreased in air agitated mixture until soil is loosened and emulsified. Remove parts from tank. Flush parts with pressure water rinse, or water boosted with air pressure.

Properties:

A clear yellow, water thin liquid with a mild odor.

Weight per gallon: 8.75#

Flash point over 180°F

Biodegradable

Contains water, alkaline phosphates, alkaline silicates, water soluble solvents and sodium chromate (less than 0.1%).

Precautions:

Store above 40°F. To restore frozen material, warm to about 80°F and agitate vigorously to redissolve solids.

Avoid contact with eyes through use of face shield.

Avoid prolonged skin contact.

In case of accidental contact, wash with soap and water.

DO NOT TAKE INTERNALLY.

The information contained herein is presented without guarantee or warranty and the Seller disclaims any liability incurred from the use thereof. Nothing contained herein is to be construed as a recommendation for any use in a commercial process not controlled by the Seller, nor for a use which is in violation of any existing patent, foreign or domestic, or of applicable laws and regulations.

THE SELLER MAKES NO WARRANTIES, EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, EXCLPT AS EXPRESSEY STATED IN SELLER'S SALES CONTRACT OR SALES ACKNOWLEDGMENT FORM.